



**Photo 1—September 11, 2020. Supersacks of material recovered from Puyallup River, stored in Conex box at Electron Main Office.**



**Photo 2—September 11, 2020. Garbage can with crumb-rubber material recovered from the Puyallup River (estimated at 5-7 cups of material).**



**Photo 3—September 11, 2020. Ford F-150 pick-up bed with material recovered from the Puyallup River. Material was transported to main office Conex box for storage.**




**Photo 4—September 11, 2020. A second Ford F-150 pick-up bed with material recovered from the Puyallup River. Material was transported to main office Conex box for storage.**




**Photo 5—September 16, 2020. Recovered material stored in Conex box (Stitched image).**



**Photo 6—September 16, 2020. Recovered material stored in Conex box (panoramic image, same material as pictured above).**



**Photo 7—September 16, 2020. Segment 1 of River visually inspected, looking upstream.**



**Photo 8—September 16, 2020. Segment 1 of River visually inspected, looking downstream**



**Photo 9—September 16, 2020. Segment 2 of River visually inspected, looking upstream.**



**Photo 10—September 16, 2020. Segment 2 of River visually inspected, looking downstream.**



**Photo 11—September 16, 2020. Detail of area of fine sediment deposition.**